FLUIDOTHERAPY DIGITAL MODEL CALIBRATION

1. Unplug the fluidotherapy from the AC outlet.

2. While pressing and holding the Start and Stop buttons simultaneously, plug the fluidotherapy back into the AC outlet.

3. CAL will appear on the display. Release the Start and stop buttons.

4. Press the Start button. The motor[s] will start and the designation 'LO' plus two digits will appear. Use the Increase or Decrease button to set the desired low end motor speed. LO16 is recommended.

5. Press the Mode button. The motor[s] will stop and the designation 'HI' plus two digits will appear. Press Start and the motor[s] will start. Use the Increase or Decrease buttons to set the desired high end motor speed. HI40 is recommended.

6. Press the Mode button to save the motor speed settings and start the speed calibration.

7. The fluidotherapy will now go through a 30 second motor speed calibration.

8. After the self calibration is completed, the designation 'PERF' will appear. If an error code should appear the complete procedure must be repeated.

9. To finish the calibration, press the 'Mode' button until 'CAL' appears on the display.

10. Unplug the fluidotherapy from the AC outlet and then plug it back into the AC outlet.

11. YOU ARE NOW FINISHED WITH THE CALIBRATION.